

The right size clothing

Pay attention to these points:

A Chest measurement:

Put the tape measure horizontally around the widest part of your chest. This is used for jackets/combinations. Example: if your chest measures 102 cm, select a 104 cm jacket (always round measurements up). If you wear a pullover under the jacket, select the next size up, i.e. 112 cm.

K Measurement for low and normal waist height:

Put the tape measure horizontally around your waist.



Hip measurement:

Put the tape measure horizontally around your hips.

E Leg length:

Measure from the crotch to the floor without wearing shoes. Normal 82 cm (32"), Long 90 cm (35").



Jackets, vest and shirts									
Size	s	М	L L	XL	2XL				
A Chest measurement (cm)	92	100	104	112	116				
A Chest measurement (inches)	36	39.5	41	44	45.5				


Trousers and shorts										
Size	C46	C47	C48	C49	C50	C51	C52	C54	C56	C58
K/L Waist size (cm)	78	80.5	83	85.5	88	90.5	93	98	103	108
K/L Waist size (inches, jeans size)	30	31	32	33	34	35	36	38	40	42
E Leg length (cm)	82	82				90				
E Leg length (inches, jeans size)	32					35				

When measuring trousers, the leg length **E** and the waist size are put together to form a combined size. For example, leg length **E=82** and waist size **K/L=78** results in a combined **size of 82C46**

Shoes and boots								
Size								
EU	40	41	42	43	44	45	46	
UK	61/2	7	8	9	10	10½	11	

Heated outdoor jacket

for work and leisure



The right size clothing -

Pay attention to these points:

- A Chest measurement: Put the tape measure horizontally around the widest part of your chest. Example: if your chest measures 102 cm, select a jacket with chest measurement of 106 cm (always round measurements up). If you wear a pullover under the jacket, select the next size up, i.e. a jacket with chest measurement of 112 cm.
- B Height / Back length: Put the tape measure vertically from your neck to your coccyx.
- **C** Arm length: Put the tape measure from your wrist to your shoulder.

Heat+ Jacket 10,8 Volt Professional Men's version								
		S	М	L	XL	XXL	3XL	
A	Chest measurement in cm	92	100	104	112	116	124	
В	Height / Back length in cm	73	74	76	76	80	80	
C	Arm length in cm	64	65	66	67	68	70	

Heat+ Jacket 10,8 Volt Professional Ladies' version								
		XS	S	М	L	XL		
A	Chest measurement in cm	78	84	90	96	102		
В	Height / Back length in cm	72	73	73	75	76		
C	Arm length in cm	59	60	61	62	63		